10/825680



Michael P. Brennan

Direct Dial: 248.641.1218

mbrennan@hdp.com

October 24, 2007

Certificate

of Correction

Director of the U.S. Patent and Trademark Office P. O. Box 1450 Alexandria, VA 22313-1450

Re:

Patent No. 6,998,803

Issued: February 14, 2006

Inventor(s): John E. Durkee et al.

Enhanced Performance for DC Motor Drive Switching

Sir:

We have noted in proofreading Patent No. 6,998,803 the following errors:

Column 1, line 27 (application page 1, line 17), "motors" should be -motor's--.

Column 1, line 29 (application page 1, line 18), "motors" should be -motor's--.

Column 1, line 30 (application page 1, line 19), "motors" should be -motor's--.

Column 1, line 31 (application page 2, line 1), "motors" should be -motor's--.

Column 1, line 48 (application page 2, line 13), after "relay", insert -in--.

Column 1, line 53 (application page 2, line 18), "coils" should be -coil's--.

Column 2, line 28 (application page 4, line 7), after "relay", insert –in--.

Kindly make these errors of record in your files.

Very truly yours,

Michael P. Brennan Reg. No. 30,612

MPB/rc

Harness, Dickey & Pierce, P.L.C. Attorneys and Counselors P.O. Box 828 Bloomfield Hills, Michigan 48303 U.S.A. 248.641.1600 • fax 248.641.0270

FOR COURIER DELIVERY ONLY 5445 Corporate Drive, Suite 200 Troy, Michigan 48098 U.S.A.